

S/053/0065  
cc: Lynn

## UTAH 3809 COMPLIANCE INSPECTION REPORT

*Contract:* U-78598

*Field Office:* UTC030

*Operator(s):* Color Country Rock –Jeff Fawcett (435 674-2434)

*Project name:* Snow White Marble Quarry

*Location:* T39S R19W Sec 9 SWSE

*Disturbance:* Operator reclaimed the two open-cuts in contact metamorphosed Callville Limestone (marble) adjacent to the Mineral Mountain rhyolitic intrusion. The workings had consisted of two open-cuts with dumps that are about 100 ft by 75 ft and 150 ft by 50 ft in size. The NW site (0.68 acres) and the SE site (0.71 acres) both total 1.39 acres of disturbance. Operator failed to reclaim the access roads that have an abundance of alfalfa, forage kochia, small burnet, side-oats grama, wheat grasses, and penstemon growing from aerial drop of seed in 2007. Operator should be able to pull in side berms and blend/rough-up the soil to remove the track of the road.

*Hazardous Materials on Site:* None/The site is stable and fairly clean.

*Comments:* No activity in last 9 years.

*Instructions to Operator:* Reclamation of roads required/contacted operator on November 23, 2010.

*Recommended Action(s):* Notice expired must reclaim- \$15,000 bond held is acceptable-contact UDOGM.

*Photographs Taken:* See photographs below.

*Date of Inspection:* November 23, 2010

*Inspector:* Russell Schreiner

Reviewed by: \_\_\_\_\_  
FM, St. George Field Office

Date: \_\_\_\_\_





View of the reclaimed northern open-cut and access road showing abundant alfalfa, kochia, small burnet, wheat grasses growing on the access road.





Closer view of the reclaimed northern open-cut and access road.





Close-up view of the reclaimed northern open-cut.





Close up of the reclaimed south open-cut (originally 15 ft wide by 60 ft long and up to 10 ft deep) in recrystallized limestone/marble.





Close up of the reclaimed south open-cut in recrystallized limestone.





View of the southern open-cut access road from above.